

DEPARTMENT OF PUBLIC HEALTH AND PREVENTIVE MEDICINE

From
Dr.J.Prabhakaran,MBBS.,DPH.,DIH.,
Deputy Director of Health Services,
Namakkal.

To
The President,
Trinity International
School (CBSE),
Mohanur Road,
Vagurampatty Village,
Namakkal Taluk & District,
Pincode: 637 002.

K. Dis.No.1707/B1/2022 Dated : 21.03.2022

Sir,

Sub: Public Health - Sanitary Certificate for the Trinity International School (CBSE), Mohanur Road, Vagurampatty Village, Namakkal Taluk & District for the year 2021 - 22 -issued.

Ref: 1. Your Letter dated: 25.02.2022
2. Inspection report dated: 17.03.2022 of the Block Health Supervisor, Govt Primary Health Centre, Ernapuram, Namakkal District.

&&&&

With reference to the above, the Sanitary Certificate for the Trinity International School (CBSE), Mohanur Road, Vagurampatty Village, Namakkal Taluk & District for the year 2021 -2022 is enclosed herewith.

Enclosure: 1


Deputy Director of Health Services,
Namakkal.


21/03/22



GOVERNMENT OF TAMILNADU

**DEPARTMENT OF PUBLIC HEALTH AND PREVENTIVE MEDICINE
SAFE DRINKING WATER AND SANITATION CONDITION CERTIFICATE**

K.Dist.No:1707/B1/2022

Date : 21 .03.2022.

It is certified that an inspection team headed by Thiru.I.Selvam, Block Health Supervisor, Government Primary Health Centre, Ernapuram inspected Trinity International School (CBSE), Mohanur Road, Vagurampatty Village, Namakkal Taluk & District - 637 002 on 17.03.2022 and found that the School has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Government of Tamilnadu.

The above Certificate is valid for a period of one year , from the date of issue.

Name : I. Selvam

Designation :

/ Counter signed /

**BLOCK HEALTH SUPERVISOR
GOVT. PRIMARY HEALTH CENTRE
ERNAPURAM, NAMAKKAL BLOCK**

Name : Dr.J.PRABHAKARAN, M.B.B.S., D.P.H.,DIH.,

Designation :

**Deputy Director of Health Services,
Namakkal.**

To
The President,
Trinity International School (CBSE),
Mohanur Road,
Vagurampatty Village,
Namakkal Taluk & District - 637 002.



Tamil Nadu Fire & Rescue Service Department

Form No. 41
Order No. 250-3

L.Dis No. 983/A/2022.
Date: 15.02.2022.

District Office,
Fire & Rescue Services,
Namakkal District.

No objection Certificate

Sub: Tamil Nadu Fire & Rescue Services – Namakkal Division – Use of Places and trades for purposes involving risk from fire – No objection Certificate – Issued.

Ref: 1. Your Letter Dated : NIL.
2. Namakal Station Officer Inspection Report Rc.No. 82/IV/2022
Date : 14.02.2022.

With reference to the letter cited above, Premises **M/s. Trinity International School (CBSE)**, S.F.No. 194/1, 194/2, 194/3 Mohanur Road, Vagurampatti Village, Namakkal Taluk & District was inspected by the Station Officer, Namakkal. There is no objection from the Fire Service point of view to No Objection Certificate the said premises for School purpose. Subject to the condition noted thereon and such other conditions as may be prescribed. This NOC is Valid for One Year.

Condition:

1. All fire and life safety measures should be provided as per National Building Code of India.

(Office Seal)



To,

M/s.Trinity International School (CBSE),
Mohanur Road,Vagurampatti Village,
Namakkal Taluk & District.

C. S. S. 15.2.2022
District Officer,
Fire & Rescue Services,
Namakkal District.

15/2/22

CERTIFICATE OF STABILITY

FORM - C

Form of Certificate of Structural soundness under sub section-4 of the Tamilnadu Public Building (licensing) Act Tamil Nadu Act 13 of 1965 referred to in rule of the Tamilnadu Public Building (Licensing) rule 1965.

I Certify that I have inspected the Building mentioned in the statement and furnish below its salient technical features.

1. Foundation :

- | | | | |
|------|---|---|--|
| i) | Depth below ground level | : | 1.80 M |
| ii) | Nature of soil met with at foundation level | : | Hand Gravelly Soil at 1.50 M below Ordinary soil |
| iii) | Pressure at foundation | : | 18.36 tons/m ² |
| iv) | Probable safe bearing capacity of the soil met with at foundation | : | 25 tons/m ² |

2. Superstructure :

- | | | | |
|-----|---|---|---|
| i) | Maximum stress in the most critical section of masonry and concrete | : | Brick masonry in
Cement mortar - 20.24 t/m ² |
| ii) | Nature of Masonry and concrete and its safe permissible stress | : | Brick masonry in C.M - 45 t/m ²
R.C.C Member - 20 N/mm ² |

The structural soundness of the building has been verified by me with reference to ISI loading standards 875 (latest version) and other relevant Indian standards code of practice and declare that the building for the purpose noted in the statement. A license may be granted for the period of 3 Years from **29.10.2021 to 28.10.2024.**


Er.R. SUNDARRAJ, B.E., M.B.A., M.I.E., F.I.V., M.Sc(Val)
CHARTERED ENGINEER
APPROVED VALUER - 5391
REGISTERED VALUER C1 / 342
DISTRICT PANEL ENGINEER CLASS 1A
APPROVED VALUER FOR BANKS
ARUN TOWERS, 105, PARAMATHI ROAD
NAMAKKAL - 637 001